


Fig. 1






FIG. 2

FIG. 3





FIG. 4

22



Mg	G	Mg	G	Mg	G
Cy	Ye	Cy	Ye	Cy	Ye
Mg	G	Mg	G	Mg	G
Cy	Ye	Cy	Ye	Cy	Ye
Mg	G	Mg	G	Mg	G





FIG. 5

FIG. 6






FIG. 7









FIG. 8



$$\sigma=0.5, n=1, m=1, \theta_g=45^\circ$$

0	0	0	0	0
0	3	21	3	0
0	21	158	21	0
0	3	21	3	0
0	0	0	0	0

/254

$$\sigma=0.5, n=3, m=1, \theta_g=45^\circ$$

0	0	0	0	0
0	5	0	0	0
0	0	247	0	0
0	0	0	5	0
0	0	0	0	0

/257

$$\sigma=0.7, n=1, m=1, \theta_g=45^\circ$$

0	1	1	1	0
1	11	30	11	1
1	30	83	30	1
1	11	30	11	1
0	1	1	1	0

/259

$$\sigma=0.7, n=3, m=1, \theta_g=45^\circ$$

0	0	0	0	0
0	26	1	0	0
0	1	199	1	0
0	0	1	26	0
0	0	0	0	0

/255

$$\sigma=0.8, n=1, m=1, \theta_g=45^\circ$$

0	1	3	1	0
1	13	29	13	1
3	29	64	29	3
1	13	29	13	1
0	1	3	1	0

/252

$$\sigma=0.8, n=3.5, m=1, \theta_g=45^\circ$$

0	0	0	0	0
0	37	1	0	0
0	1	177	1	0
0	0	1	37	0
0	0	0	0	0

/255

$$\sigma=0.9, n=1, m=1, \theta_g=45^\circ$$

0	2	4	2	0
2	15	27	15	2
4	27	51	27	4
2	15	27	15	2
0	2	4	2	0

/251

$$\sigma=0.9, n=4, m=1.25, \theta_g=45^\circ$$

0	0	0	0	0
0	28	1	0	0
0	1	195	1	0
0	0	1	28	0
0	0	0	0	0

/255

$$\sigma=1.0, n=1, m=1, \theta_g=45^\circ$$

1	3	6	3	1
3	15	25	15	3
6	25	41	25	6
3	15	25	15	3
1	3	6	3	1

/253

$$\sigma=1.0, n=4.5, m=1.5, \theta_g=45^\circ$$

0	0	0	0	0
0	22	1	0	0
0	1	209	1	0
0	0	1	22	0
0	0	0	0	0

/257

FIG. 9

90

0	0	0	0	0
0	28	1	0	0
0	1	195	1	0
0	0	1	28	0
0	0	0	0	0

FIG.10

FIG. 11




Fig. 12

